

1/16

Fig.2(a)




Fig. 2(b)




Fig.3




Fig. 4





Fig.5






Fig.7A





Fig.7B






Fig.7D




Fig.7E






Fig.7F





设施 湖道。

Fig.7H

METAL ELECTRODE

INTERLAYER INSULATING FILM

Gate

CHANNEL DRAIN
(STI)

10/16

101509662

Fig.8(a)




Fig.8(b)





Fig.9




12/16


PAGE 48/61 \* RCVD AT 9/28/2004 6:36:16 AM [Eastern Daylight Time] \* SVR:DCNTFAX01/0 \* DNIS:6285116 \* CSID:81354701911 \* DURATION (mm-ss):17-10

The state of the state of

Fig.10




13/16




747 C
PAGE 50/61 \* RCVD AT 9/28/2004 6:36:16 AM [Eastern Daylight Time] \* SVR:DCNTFAX01/0 \* DNIS:6285116 \* CSID:81354701911 \* DURATION (mm-ss):17-10


Fig.12



15/16

Fig.13





16/<sub>16</sub>